

**HP3-024**

**HP3-024**

**HP Color LaserJet 4700 series**

**Version 3.1**

## HP3-024

### QUESTION NO: 1

The HP Color LaserJet 4700 automatically calibrates and cleans at certain times to maintain optimum print quality. Which of the following conditions cause the device to perform a color-plane registration (CPR)? Select THREE.

- A. one or more print cartridges are installed that have not previously been installed in the printing device
- B. 10,000 pages have printed since the last calibration
- C. 'Full Calibrate Now' is requested through the control panel
- D. the ETB is replaced

**Answer:** A, C, D

### QUESTION NO: 2

Before performing an engine test on the HP Color LaserJet 4700ph+,\_\_\_\_\_.

- A. the printing device must be powered off
- B. the printing device must be power-cycled
- C. the output device connection cable must be detached from the printing device
- D. the output device and output accessory bridge must be removed

**Answer:** B

### QUESTION NO: 3

Automatic calibration occurs for which events? Select THREE.

- A. whenever the device comes out of power save mode
- B. when the printer is powered on after having been powered down for longer than 20 seconds
- C. whenever a brand new print cartridge is installed in the printer
- D. when 1,000 pages have printed since the last calibration

**Answer:** B, C, D

### QUESTION NO: 4

For what reason should you disassemble and then replace the paper feed assembly?

- A. if repeated paper jams occur due to excessive paper skew
- B. if replacing feed rollers and adjusting paper skew sensors do not solve repeated jam errors
- C. if the media sensor value no longer matches the value on the label located on the paper feed assembly